

| | | |
|---|---|---|
| <p>DET 1-3</p> <p>450</p> <p>DET 4</p> | <p>450</p> <p>Betoni Concrete</p> <p>350x350</p> <p>150</p> | <p>① 905155 PCS 4</p> |
| <p>DET 1</p> <p>Ø16/8.4 (909256)</p> <p>M8x45 (909247)</p> | <p>DET 2</p> <p>M8x35 (909855)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>② 003493 PCS 4</p> |
| <p>DET 3</p> <p>M8x60 (909866)</p> <p>Ø24/8.4 (980152)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>DET 4</p> <p>M8 (980160)</p> <p>Ø16/8.4 (909256)</p> <p>M8x35 (909855)</p> | <p>③ 909855 PCS 8</p> <p>M8x35</p> |
| <p>DET 1</p> <p>M8x60 (909866)</p> <p>M8x45 (909247)</p> | <p>DET 2</p> <p>M8x35 (909855)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>④ 909866 PCS 4</p> <p>M8x60</p> |
| <p>DET 3</p> <p>M8x60 (909866)</p> <p>Ø24/8.4 (980152)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>DET 4</p> <p>M8 (980160)</p> <p>Ø16/8.4 (909256)</p> <p>M8x35 (909855)</p> | <p>⑤ 909247 PCS 4</p> <p>M8x45</p> |
| <p>DET 1</p> <p>M8x60 (909866)</p> <p>M8x45 (909247)</p> | <p>DET 2</p> <p>M8x35 (909855)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>⑥ 980152 PCS 4</p> <p>Ø24/8.4</p> |
| <p>DET 3</p> <p>M8x60 (909866)</p> <p>Ø24/8.4 (980152)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>DET 4</p> <p>M8 (980160)</p> <p>Ø16/8.4 (909256)</p> <p>M8x35 (909855)</p> | <p>⑦ 909256 PCS 16</p> <p>Ø16/8.4</p> |
| <p>DET 1</p> <p>M8x60 (909866)</p> <p>M8x45 (909247)</p> | <p>DET 2</p> <p>M8x35 (909855)</p> <p>Ø16/8.4 (909256)</p> <p>M8 (980160)</p> | <p>⑧ 980160 PCS 8</p> <p>M8</p> |