







| | | | |
|---|-----|---|-----|
| ① 905858 | PCS | ② 909628 | PCS |
|  | 2 |  | 4 |
| 1200x80x90 | | M10x100 | |
| | PCS | | PCS |
| | | | |
| | PCS | | PCS |
| | | | |
| | PCS | | PCS |
| | | | |
| | PCS | | PCS |
| | | | |
| | PCS | | PCS |
| | | | |
| | PCS | | PCS |
| | | | |

| | | |
|--|--|--|
| <p>DET 1</p>  <p>Access- and maintenance panel. Asennus- ja huolto luukku.</p> | <p>DET 2</p>  <p>905850</p> <p>M12</p> <p>Ø44/13.5</p> | <p>DET 3</p>  |
| <p>DET 4</p>  <p>Ø10</p> <p>90</p> <p>S</p> <p>90</p> <p>CONCRETE</p> <p>M10x100</p> | | |
| | | |
| | | |